







Т	Ε	S	Т	S	С	Н	Ε	D	U	L	

ST PITS	ΡΕ	R	С			Т	E S	T S
		RUN NUMBER						DEDTU
DESCRIPTION	PT No.	1	2	3 4 5		5	PRESOAKED	DEPTH
SISTS OF 14" GRAVELLY CLAY LOAM; BALANCE IS HARD PAN SILT	1	40	44	-	-	-	YES	19"
DNSISTS OF 16" GRAVELLY CLAY LOAM; BALANCE IS HARD PAN SILT	2	15	8	8	-	-	YES	14"
SISTS OF 18" GRAVELLY LOAM; BALANCE IS HARD PAN TO ROCK	3	1	1	_	-	_	YES	24"
SISTS OF 30" GRAVELLY CLAY; BALANCE IS HARD PAN TO ROCK	4	2	5	_	-	-	YES	16"
SISTS OF 30" GRAVELLY CLAY; BALANCE IS HARD PAN TO ROCK	PERCOLATION TESTS PERFORMED ON THE DAY OF NOVEMBER 20, 2019.							20 2010
SISTS OF 30" GRAVELLY CLAY; BALANCE IS HARD PAN TO ROCK	TEST HOLES PREDUG AND PRESOAKED 24 HOURS EARLIER AS PER DCHD							
NSISTS OF 30" GRAVELLY CLAY; BALANCE IS HARD PAN TO ROCK	REQUIREMENTS.							
OCTOBER 18 2019 BY THE OFFICE OF M GILLESPIE & ASSOCIATES CONSULTIN	1 -							

l L	- E	F	ΙE	L D	C	6 C	h e d u	LΕ	
.L JIRED	TRENCH WIDTH	LATERAL SPACING	DROP BOX	CURTAIN DRAIN	DISPOSAL SYSTEM	MIN. RAW INVERT	SEPTIC TANK SIZE 4 BEDROOM 5 BEDROOM		OF LATERALS 5 BEDROOM
_	2'-0"	6'-0"	NO	NO			1250 GAL. 1500 GAL.	8 LATS @ 55'	10 LATS @ 55'
-	2'-0"	6'-0"	NO	NO			1250 GAL. 1500 GAL.	4 LATS @ 46'	5 LATS @ 46'

